



USE COPPER OR ALUMINUM WIRE

CHART A		FACTORY WIRING		FIELD WIRING	
	42WH	148WH5 v	Low Voltage	-----	-----
Fuse A	50A T.D.	60A T.D.	High Voltage	-----	-----
Fuse B	60A STANDARD				
FUSE C	30A STANDARD				

All fuses Class K5.

- ⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.
- ⚠ For 208V operation move this wire to 208V transformer tap.