



CHART A		FACTORY WIRING	FIELD WIRING
42WH	48WH5	Low Voltage	-----
50A TD	60A TD	High Voltage	-----
Type B 160A STANDARD			

ALL FUSES CLASS K5

⚠ If there is an X1 and X2 terminal ⚠ For 208V operation move this wire to 208V transformer tap. and connect from C to either one.

USE COPPER OR ALUMINUM WIRE