



230/208-60-1
1-09-88-02

	FACTORY WIRING	FIELD WIRING
Low Voltage	—————	-----
High Voltage	—————	-----

USE COPPER OR ALUMINUM WIRE

- ⚠ USED ON MAC30 MODELS ONLY.
- ⚡ MAC30 : 35/5 - 370
MAC36 : 35/5 - 440
- ⚠ FOR 208V. OPERATION MOVE THIS WIRE TO 208V. TRANSFORMER TAP.

NOTE: FUSE A - 60A TIME DELAY
FUSE B - 30A
ALL FUSES TYPE K-5