

TS0-WG3 and TSO-WG5 TOP OUTLET INSTALLATION INSTRUCTIONS FOR WG SERIES MODELS



Bard Manufacturing Company, Inc.
Bryan, Ohio 43506

1. Kit contains (1) top with supply outlet installed and (1) solid upper back.
2. Remove current parts and replace with parts supplied.

REMOVE TOP
AND REPLACE
WITH TOP
SUPPLIED

REMOVE
UPPER BACK
AND REPLACE
WITH BACK
SUPPLIED

BEFORE CONVERSION

*NOTE: MAKE SURE NOT TO
TEAR INSULATION
DURING CONVERSION*

POSITION TOP WITH SUPPLY OPENING
TOWARDS THE BACK OF THE UNIT AS
SHOWN

AFTER CONVERSION


BACK WITHOUT
SUPPLY OPENING

 **NOTE**

**See reverse side for important
installation and clearance information.**

MIS-1532

1" CLEARANCE TO COMBUSTIBLE MATERIALS FOR THE FIRST 3 FEET OF THE SUPPLY PLENUM



MIS-1552