



Fused Disconnect Switch

460V 60 Hz 3-Ph

Factory Wiring \_\_\_\_\_  
Field Wiring - - - - -

USE COPPER OR ALUMINUM WIRE

⚠ Add jumper Rc to Rh.

⚠ Set heat anticipator for W1 at .40A.

MODELS  
42WA, 49WA, 60WA  
6, 9, 12, 15Kw

4010-320G