



USE COPPER OR ALUMINUM WIRE

CHART A

	42WH	48WH5 v
Fuse A	50A T.D.	60A T.D.
Fuse B	60A STANDARD	
FUSE C	30A STANDARD	

All fuses Class K5.

	FACTORY WIRING	FIELD WIRING
Low Voltage	_____	-----
High Voltage	_____	-----

MODEL
42WH, 48WH5
HEAT PUMP
15 Kw

- ⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.
- ⚠ For 208V operation move this wire to 208V transformer tap.