



USE COPPER OR ALUMINUM WIRE

CHART A		FACTORY WIRING	FIELD WIRING
Fuse A	50A T.D.	---	---
Fuse B	60A STANDARD	---	---
FUSE C	30A STANDARD	---	---

- All fuses Class K5.
- ⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.
- ⚠ For 208V operation move this wire to 208V transformer tap.