



USE COPPER OR ALUMINUM WIRE

CKTA
 ↓ ↓ ↓
 230/208-60-3

FACTORY WIRING	FIELD WIRING
Low Voltage ———	—————
High Voltage ———	—————

⚠ If there is an X1 and X2 terminal on Q674L1181 jumper them together and connect from C to either one.
 ⚠ For 208V operation move this wire to 208V transformer tap.

MODEL
 42WH-3, 48WH5-3
 HEAT PUMP
 w/9KW

4014-221C