



Fuse A - 45A Time Delay
 Fuse B - 40A STD 12Kw,
 45A STD 15Kw

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.
 ⚠ For 208V operation move this wire to 208V transformer tap.

MODEL
 48WH2, 48WH5
 HEAT PUMP
 w/12, 15 Kw

230/208-60-3

USE COPPER OR ALUMINUM WIRE

FACTORY WIRING		FIELD WIRING	
Low Voltage	—————	Low Voltage	-----
High Voltage	—————	High Voltage	-----