



▲ If there is an X1 and X2 terminal on Q674L1181, Jumper them together and connect from C to either one.
 ▲ For 208V operation move this wire to 208V transformer tap.

CKT. A
 CKT. B

230/208-60-3

USE COPPER OR ALUMINUM WIRE

FACTORY WIRING	FIELD WIRING
Low Voltage ———	-----
High Voltage - - - - -	-----

4014-231:H