


T872N1036/Q672F1299 or T874N1024/Q674F1261

T872R1164/Q672L1185

T874R1129/Q674L1181



(See Chart A) Fuse Panel

CHART A	
42WH-3	48WH5-3
Fuse A	40A T.D. 45A T.D.
Fuse B	60A Standard

FACTORY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	-----

MODEL
42WH-3, 48WH5-3
HEAT PUMP
w/18KW

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.

⚠ For 208V operation move this wire to 208V transformer tap.

4014-240P

USE COPPER OR ALUMINUM WIRE

230/208-60-3