

T872N1036/0672F1299 or T874N1024/0674F1261

T872R1164/0672L1185
T874R1128/0674L1181




CHART A	
	42WH-3 48WH5-3
Fuse A	40A T.D. 45A T.D.
Fuse B	60A Standard

ALL FUSES CLASS K5

FACTORY WIRING	FIELD WIRING
Low Voltage	-----
High Voltage	-----

MODEL
42WH-3, 48WH5-3
HEAT PUMP
w/18KW

⚠ If there is an X1 and X2 terminal on 0674L1181, jumper them together and connect from C to either one.

230/208-60-3

⚠ For 208V operation move this wire to 208V transformer tap.

4014-240R