



USE COPPER OR ALUMINUM WIRE

CHART A

48WH5 v	FACTORY WIRING	FIELD WIRING
60A I.D.	Low Voltage	-----
60A STANDARD	High Voltage	-----
30A STANDARD		

All fuses Class K5.

- ⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.
- ⚠ For 208V operation move this wire to 208V transformer tap.