



CHART A

	42WH-3	48WH5-3
Fuse A	40A T.D.	45A T.D.
Fuse B	40A Standard for 12Kw	45A Standard for 15Kw

230/208-50-3

⚠ If there is an X1 and X2 terminal on Q674L1181, Jumper them together and connect from C to either one.
 ⚠ For 208V operation move this wire to 208V transformer tap.

ALL FUSES CLASS K5

USE COPPER OR ALUMINUM WIRE

FACTORY WIRING **FIELD WIRING**
 Low Voltage —————
 High Voltage - - - - -