



⚠ Reroute jumper from X2-W2 to X2-E.

⚠ Set heat anticipators at .40A.