



230/208-60-3

Fuse A - 45A Time Delay
 Fuse B - 40A STD 12Kw,
 45A STD 15Kw

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.
 ⚠ For 208V operation move this wire to 208V transformer tap.

MODEL
 48WH5
 W/ 12, 15KW

USE COPPER OR ALUMINUM WIRE

FACTORY WIRING FIELD WIRING
 Low Voltage ———
 High Voltage - - - -

4014-810B