


T874C1000 THERMOSTAT  
Q674A1001 SUBBASE

G R Y W1 W2

T87F THERMOSTAT  
Q539F SUBBASE  
OR  
IF56 THERMOSTAT

Rh G Rc Y W



BK - BLACK	O - ORANGE
BL - BLUE	PR - PURPLE
BR - BROWN	R - RED
GR - GRAY	Y - YELLOW
G - GREEN	W - WHITE

USE COPPER OR ALUMINUM WIRE

	FACTORY WIRING	FIELD WIRING
LOW VOLTAGE		
HIGH VOLTAGE		