



**DANGER: ELECTRICAL SHOCK HAZARD, DISCONNECT POWER BEFORE SERVICING**

MODEL	CIRCUIT BREAKER
WAG36A-C54C	15A
WAG40A-C54C	20A

- SET HEAT ANTICIPATOR AT .6 A
- FOR 208V OPERATION MOVE THIS WIRE TO 208V TRANSFORMER TAP
- ADD JUMPER R<sub>c</sub> - R<sub>h</sub>

**USE COPPER OR ALUMINUM WIRE**

	FACTORY WIRING	FIELD WIRING
Low Voltage		
High Voltage		