



USE COPPER CONDUCTORS ONLY  
SUITABLE FOR AT LEAST 75° C

COMPONENT CODE	
CC	COMPRESSOR CONTACTOR
COMP	COMPRESSOR
DFC	DEFROST CONTROL
EHR	EMERGENCY HEAT RELAY
GND	GROUND
H1	HEAT STRIP #1
H2	HEAT STRIP #2
HC1	HEATER CONTACTOR #1
HC2	HEATER CONTACTOR #2
HPC	HIGH PRESSURE CONTROL
IBC	INDOOR BLOWER CAPACITOR
IBM	INDOOR BLOWER MOTOR
IBR	INDOOR BLOWER RELAY
LAB	LOW AMBIENT BYPASS
LAC	LOW AMBIENT CONTROL
LBP	LOW PRESSURE BYPASS
LPC	LOW PRESSURE CONTROL
LS	LIMIT SWITCH
DFC	OUTDOOR FAN CAPACITOR
OFM	OUTDOOR FAN MOTOR
DFR	OUTDOOR FAN RELAY
PL1	PLUG #1
PD	PULL DISCONNECT
PM	PHASE MONITOR
RV	REV. VALVE SOLINOID
SK	START KIT
T	TRANSFORMER
TB	TERMINAL BLOCK
TBL	LOW VOLTAGE TERMINAL BLOCK
TCO	THERMAL CUTOFF

⚠️, ⚠️ LABELED WIRES CONNECT IF NO OPTIONS USED. ⚠️ FOR LOW & MEDIUM SPEEDS CONNECT ORANGE TO BLACK. RED (LOW) OR BLUE (MEDIUM) TO T1 OF IBR. FOR HIGH SPEED TAPE ORANGE, RED, BLUE LEADS SEPARATELY. CONNECT BLACK TO T1 OF IBR.

HIGH VOLTAGE	FACTORY STD.			FIELD			OPTIONAL			COLOR CODE			BARD MFG. CO. 4096-326 C			
	---	---	---	---	---	---	---	---	---	---	---	---				
BLACK	BK	BLACK	Y	YELLOW	V	VIOLET	T	TAN	BK	BLACK	Y	YELLOW	V	VIOLET	T	TAN
BROWN	BR	BROWN	G	GREEN	(PR)	PURPLE	PK	PINK	BR	BROWN	G	GREEN	(PR)	PURPLE	PK	PINK
RED	R	RED	BL	BLUE	GY	GRAY	L	LAVENDER	R	RED	BL	BLUE	GY	GRAY	L	LAVENDER
ORANGE	O	ORANGE	W	WHITE	(S)	SLATE			O	ORANGE	W	WHITE	(S)	SLATE		