



Ladder Diagram

Standard Diagram

WIRING IDENTIFICATION NUMBERS FOR BARD USE ONLY.

	Factory	Field	Optional
High Voltage			
Low Voltage			

WARNING
 USE COPPER CONDUCTORS ONLY SUITABLE FOR AT LEAST 75° C.

DANGER
 ELECTRICAL SHOCK HAZARD DISCONNECT POWER BEFORE SERVICING.

Bard
 Bard Mfg. Co.
 Bryan, Ohio
 4096-354