



- ⚠ FOR ANTIFREEZE LOOP APPLICATIONS, CHANGE LOW PRESSURE SWITCH TO YELLOW LEADS ON YELLOW WIRES COMING OFF OF COMPRESSOR CONTROL MODULE "LPC" TERMINALS
- ⚠ REMOVE JUMPER WHEN CS2000 ENERGY MONITOR IS INSTALLED
- ⚠ REMOVE WIRE FROM TERMINAL Y2 AND TAPE OFF WHEN LOWER FULL LOAD CFM DESIRED

STEPDOWN TRANSFORMER CLASS CC FUSE

MODEL	W / ERV	NO ERV
QW2S	5	3.2
QW3S	5	3.2
QW4S	7	3.2
QW5S	7	5

Wire Identification numbers for Bard use only.

WARNING
USE COPPER CONDUCTORS, ONLY SUITABLE FOR AT LEAST 75°C.

	Factory	Field	Optional
High Voltage	---	---	---
Low Voltage	---	---	---

Bard
Bard Mfg. Co.
Bryan, Ohio
4113C301 B

COMPOSITE WIRING DIAGRAM
460-60-3

⚠ DANGER
ELECTRICAL SHOCK HAZARD. DISCONNECT POWER BEFORE SERVICING.