



STEPDOWN TRANSFORMER CLASS CC FUSE

MODEL	W / ERV	NO ERV
QW2S	5	3.2
QW3S	5	3.2
QW4S	7	3.2
QW5S	7	5

⚠ DANGER
ELECTRICAL SHOCK HAZARD
DISCONNECT POWER BEFORE
SERVICING.

Wire Identification numbers for Bard use only.

	Factory	Field	Optional
High Voltage	---	---	---
Low Voltage	---	---	---

⚠ WARNING
USE COPPER CONDUCTORS,
ONLY SUITABLE FOR AT LEAST
125°C.

Bard
Bard Mfg. Co.
Bryan, Ohio
4113C301 C

COMPOSITE WIRING DIAGRAM
460-60-3