



**CHART A**

	42WH	48WH5
Fuse A	50A TD	60A TD
Fuse B	160A STANDARD	

	FACTORY WIRING	FIELD WIRING
Low Voltage	_____	-----
High Voltage	_____	-----

MODEL  
42WH, 48WH5  
HEAT PUMP  
20 Kw

ALL FUSES CLASS K5  
 ⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.  
 ⚠ For 208V operation move this wire to 208V transformer tap.

**USE COPPER OR ALUMINUM WIRE**