


18/2NI036/Q67ZF1299 or 18/4NI024/Q674F1261

T872R1164/Q672L1185  
T874R1129/Q674L1181



⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.

USE COPPER OR ALUMINUM WIRE

	FACTORY WIRING	FIELD WIRING
Low Voltage	_____	-----
High Voltage	_____	-----

MODEL  
42WH-3 48WH5-3  
HEAT PUMP  
0 Kw

⚠ For 208V operation move this wire to 208V transformer tap **4014-2110**

230/208-60-3