



CKTA
 USE COPPER OR ALUMINUM WIRE
 230/208-60-3
 Equip. Ground
 Thermal Cut-off
 Electric Heater
 If there is an X1 and X2 terminal on Q674L1181 jumper them together and connect from C to either one.
 For 208V operation move this wire to 208V transformer tap.
 MODEL 42WH-3, 48WH5-3 HEAT PUMP w/ 9 KW
 4014-221 D
 FACTORY WIRING FIELD WIRING
 Low Voltage High Voltage