



CHART A

Fuse A	42WH-3	48WH5-3
Fuse B	40A T.D.	45A T.D.
	40A Standard for 12Kw	45A Standard for 15Kw

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.
 ⚠ For 208V operation move this wire to 208V transformer tap.

MODEL
 42WH-3, 48WH5-3
 HEAT PUMP
 w/12, 15 Kw

USE COPPER OR ALUMINUM WIRE

FACTORY WIRING **FIELD WIRING**
 Low Voltage ————
 High Voltage ————

4014-230N