



▲ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one. 240V only use this.

MODEL
42WH-3, 48WH5-3
HEAT PUMP

USE COPPER OR ALUMINUM WIRE

	FACTORY WIRING	FIELD WIRING
Low Voltage	—————	- - - - -
High Voltage	—————	—————

4014-231 B