



USE COPPER OR ALUMINUM WIRE

If there is an X1 and X2 terminal on 0674L1181, jumper them together and connect from C to either one.

For 208V operation move this wire to 208V transformer tap.

FACTORY WIRING	FIELD WIRING
Low Voltage ———	-----
High Voltage ———	-----

MODELS  
42WH-3, 48WH-3  
Heat Pump  
9, 12, 15 KW

Fused Disconnect Switch

460-60-3

4014-320R