



⚠ If there is an X1 and X2 terminal on Q674L1181, Jumper them together and connect from C to either one.

MODEL
4BWH2
HEAT PUMP
18 Kw

FACTORY WIRING	FIELD WIRING
Low Voltage ———	-----
High Voltage ———	-----

USE COPPER OR ALUMINUM WIRE

Fused Disconnect Switch

460-60-3