



T872N1036/Q672F1299 or T874N1024/Q674F1261  
 T872R1164/Q672L1185  
 T874R1129/Q674L1181

**CHART A**

|        |                       |                       |
|--------|-----------------------|-----------------------|
|        | 42UH-3                | 48WH5-3               |
| Fuse A | 40A T.D.              | 45A T.D.              |
| Fuse B | 40A Standard for 12Kw | 45A Standard for 15Kw |

⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.  
 ⚠ For 208V operation move this wire to 208V transformer tap.

230/208-50-3

ALL FUSES CLASS K5

**USE COPPER OR ALUMINUM WIRE**

**FACTORY WIRING**    **FIELD WIRING**  
 Low Voltage ————  
 High Voltage - - - - -