



⚠ If there is an X1 and X2 terminal on Q674L1181, jumper them together and connect from C to either one.

⚠ For 208V operation move this wire to 208V transformer tap.

FACTORY WIRING FIELD WIRING

Low Voltage ————
High Voltage - - - - -

MODELS
42WH-3, 48WH5-3
Heat Pump
0 KW

USE COPPER OR ALUMINUM WIRE

Fused Disconnect Switch