



Standard Diagram

Ladder Diagram

Wires Connect if Option Not Used	Factory	Field	Optional
	High Voltage		
Low Voltage			

WARNING
USE COPPER CONDUCTORS ONLY SUITABLE FOR AT LEAST 75° C.

DANGER
ELECTRICAL SHOCK HAZARD. DISCONNECT POWER BEFORE SERVICING.

Bard
Bard Mfg. Co.
Bryan, Ohio
4096-349 C