



<p>A Wires Connect if Option Not Used</p> <p>High Voltage</p> <p>Low Voltage</p>	Factory	Field	Optional

(99) Wire Identification numbers for Bard use only.

B For low speed connect black and orange wires together and insulate. Connect red wire to terminal 1 of IBR.

WARNING
USE COPPER CONDUCTORS ONLY SUITABLE FOR AT LEAST 75° C.

DANGER
*ELECTRICAL SHOCK HAZARD *DISCONNECT POWER BEFORE SERVICING.



Bard Mfg. Co.
Bryan, Ohio

4096-351