



- ▲ FOR ANTIFREEZE LOOP APPLICATIONS, CHANGE LOW PRESSURE SWITCH TO YELLOW LEADS ON YELLOW WIRES COMING OFF OF COMPRESSOR CONTROL MODULE 'LPC' TERMINALS
- ▲ REMOVE JUMPER WHEN CS2000 ENERGY MONITOR IS INSTALLED
- ▲ REMOVE WIRE FROM TERMINAL Y2 AND TAPS OFF WHEN LOWER FULL LOAD CFM DESIRED

MODEL	W / ERV	NO ERV
GW2S	5	3.2
GW3S	5	3.2
GW4S	7	3.2
GW5S	7	5

	Factory	Field	Optional
High Voltage			
Low Voltage			

Wire Identification numbers for Bard use only.

DANGER
FEDERAL SHOCK HAZARD.
RECONNECT POWER BEFORE REPAIRING.

WARNING
USE JUMPER CONDUCTORS ONLY SUITABLE FOR AT LEAST 25°C.

Bard Mfg. Co.
Bryan, Ohio
4113C300 C

COMPOSITE WIRING DIAGRAM
460-60-3